Regarding Quality Control Certificate

Name of Work: **Impovements to Roads and Construction of Culverts at MSPalya Salim House to Ali House Road in Ward No. 11 (Kuvempunagara), Vidyaranyapura Sub Division.**

Job No: **011-14-000012**

Work Order No:493/22-02-2014

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT & H at this stage is not feasible since this work was executed ------ Year back.

Executive Engineer 26/3
Byatarayanapura Division
Bruhat Bangalore Mahanagara Palike